

# HHO CARBON CLEANER 6.0 for car



# King Kar

Kingkar Eco-Technologies Co.,Ltd

# Carbon deposit removal test report 01



Date of test procedure: 2016/04/03

Vehicle: LAND ROVER FREELANDER II;

Displacement: 2.2T(Turbo);

Kilometers: 114,182

Emission Type	Before	After 10min	After 20min	After	Emission reduction
CO (%)	0.68	0.39	0.28	0.17	75%
HC (ppm)	414	232	128	99	76%
CO <sub>2</sub> (%)	13.8	14.0	14.2	14.5	-5%
O <sub>2</sub> (%)	1.45	1.40	1.20	1	31%
NO <sub>x</sub> (ppm)	73	62	27	18	75%



# Carbon deposit removal test report 02

Date of test procedure: 2016/04/17

Vehicle: **BYD L3**;

**Displacement: 1.5T(Turbo)**;

**Kilometers: 46,110**

Emission Type	Before	After 10min	After 20min	After	Emission reduction
CO (%)	0.70	0.37	0.25	0.16	77%
HC (ppm)	414	238	145	92	78%
CO <sub>2</sub> (%)	14.1	14.3	14.5	14.7	-4%
O <sub>2</sub> (%)	1.48	1.33	1.20	1.01	32%
NO <sub>x</sub> (ppm)	75	60	25	17	77%

